

JON M. HUNTSMAN, JR. Governor

> GARY HERBERT Lieutenant Governor

Department of Environmental Quality

Richard W. Sprott Executive Director

DIVISION OF SOLID AND HAZARDOUS WASTE Dennis R. Downs *Director*

December 4, 2008

Lester Lemmon Operation Manager Wasatch Regional Landfill 675 South Gladiola Salt Lake City, Utah 84104

Subject: November 26, 2008 Landfill Inspection

Dear Mr. Lemmon:

On November 26, 2008 Rob Powers, a member of the solid waste section of the Division, conducted an inspection of the Wasatch Regional Landfill (WRL). The purpose of the inspection was to determine compliance with the **Utah Solid Waste Permitting and Management Rules** and the WRL landfill permit (#0501). Enclosed is a copy of the inspection photographs and the inspection checklist.

Overall the facility is clean and is professionally operated and all areas inspected met the permit or requirements of the rules

If you have any questions, please feel free to contact either Rob Powers or Ralph Bohn with the solid waste section at 801-538-6170.

Sincerely,

Original Document signed by Dennis R. Downs on 12/4/08

Dennis R. Downs, Executive Secretary
Utah Solid and Hazardous Waste Control Board

DRD/RDP/kk

Enclosures: Inspection Photographs, Inspection Checklist

c: Kirk Treece, Wasatch Regional Landfill, Inc.
 Darin Olson, ECDC Environmental Field Office
 Kurt Higgins, State of Utah School and Institutional Trust Lands Administration
 Myron Bateman, E.H.S., M.P.A., Health Officer, Tooele County Health Department

SOLID WASTE FACILITY INSPECTION REPORT CHECKLIST

UTAH DIVISION OF SOLID & HAZARDOUS WASTE

| Facility Name Wasatch Regional Class V Landfill | County Tooele |
|-----------------------------------------------------------------------|----------------------------------------------------------------|
| Location 8833 North Rowely Road, Skull Valley, Utah. | |
| Inspection Date 11/26/08 Time In 9:30 am Time O | ut Noon |
| Routine Oversight | |
| ē — i — ē | • |
| | rtly cloudy and about 50 degrees |
| Inspection Goal Compliance with the permit and the solid waste rules. | |
| Facility Contact Les Lemmon | |
| Participants Les Lemmon | |
| FOLLOW UP INSPECTION NEEDED Yes No | Recommended Follow Up Date |
| | |
| (X - indicates items | reviewed) |
| 1. PRE-INSPECTION REVIEW | |
| 1.1 Permit Review | |
| M 124 ID ID | 2.14 Other |
| 1.2 Annual Report Review | |
| ☐ 1.3 Previous Inspection Review | 4. GLONG DECLUDED / DRODEDL W BOOMED |
| 1.5 Frevious hispection review | 3. SIGNS REQUIRED / PROPERLY POSTED 3.1 Operating Days / Hrs. |
| | 5.1 Operating Days / This. |
| | ☐ 3.2 Directions & Procedure |
| 1.5 Facility Contacted (if announced inspection) | |
| | |
| 1.6 Local Heath Contacted | |
| 1.7 Other | 3.4 List of Unacceptable Materials |
| 1.7 Other | 3.5 Other |
| | |
| 2. FACILITY / OPERATIONAL CONTROLS | |
| | 4. OPERATOR / REPRESENTATIVE / EMPLOYEES |
| Looked real clean, they had two workers collecting trash 2.2 Roads | 4.1 On-site while open |
| Watered whenever necessary | |
| 2.3 Gate House Operations | ☐ 4.2 Training |
| | Reviewed all the training logs |
| | 4.3 Other |
| | |
| 2.5 Communications | 5 MONITODING |
| Hand held radios | 5. MONITORING 5.1 Methane |
| 2.6 Recycling Area | 5.1 Wednane |
| | |
| | Reviewed the protocol at the facility |
| | |
| | N CAG INV |
| 2.9 Scavenging Control | ∑ 5.4 Ground Water |
| Not allowed at facility | 5.5 Other |
| ∑ 2.10 Open Burning Not allowed | |
| 2.11 Fences, Gates, Locks, Access Control | |
| 2.11 1 010005, 04005, 200405, 1100055 CONITO | 6. DRAINAGE / EROSION |
| | S. BRATINGET EROSION 6.1 Water Run-on |
| See photos attached | |
| | |

SOLID WASTE FACILITY INSPECTION REPORT

| 9.7 Final Cover |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| |
| \[\begin{array}{cccccccccccccccccccccccccccccccccccc |
| 9.8 Self Inspection (Quarterly) Reports |
| |
| 9.9 Deviation from Plans |
| |
| 9.10 Permit, Permit Application and Rules Available |
| |
| 9.11 Other |
| |
| 40. 1.01. |
| 10. MONITORING / SAMPLING / ANALYSIS RECORDS |
| ☐ 10.1 Explosive Gas Monitoring |
| |
| ☐ 10.2 Leachate Sampling & Treatment |
| M 100G IVI C IV |
| ☐ 10.3 Ground Water Sampling Results |
| □ 10.4 Others |
| □ 10.4 Other |
| |
| 11 CDECIAL WASTE DECODDS |
| 11. SPECIAL WASTE RECORDS 11.1 Lab Analysis Results |
| 11.1 Lab Analysis Results |
| 11.2 Manifests |
| 11.2 Manifests |
| 11.3 Treatment Certification |
| 11.3 Treatment Certification |
| ☐ 11.4 Paint Filter Test Results |
| |
| ☐ 11.5 Onsite Treatment Documentation |
| |
| 11.6 Other |
| |
| 44 (377) 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 |
| 12. SPECIAL PERMIT REQUIREMENTS |
| |
| |
| 12.2 |
| |
| 12.3 |
| |
| 13. OTHER ITEMS |
| ☐ 13.1 Notice of Inspections Form Completed and Signed |
| |
| |
| - |
| □ 13.3 |
| |
| □ 13.4 |
| |
| □ 13.5 |
| 1 1 |
| 1 - |
| 1 |
| La company de la |
| |


11/26/08

Date:

DSHW Inspector Name (type or print): Rob Powers



A view of the working face in the new Phase 2B Expansion Cell





The new Phase 2B Expansion Cell is filling up fast





Getting ready to move the tipper to the east to start a new working face





Preparing the area for the new cell to the west of the present Phase 2B Expansion Cell
This area will be the new Phase 1C Expansion Cell

